

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L9	44	(burnishing) and (stress or pressure or force) adj (distribution)	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:32
2	BRS	L10	1	(burnishing) and (compression) adj (distribution)	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:33
3	BRS	L11	0	(burnishing) and (desired adj residual adj stress adj distribution)	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:33
4	BRS	L12	0	desired adj residual adj stress adj distribution	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:35
5	BRS	L13	2	burnishing with (stress adj distribution)	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:40
6	BRS	L14	0	burnishing with (stress adj2 profile)	USPAT; EPO; JPO; DERWEN T; IBM TDB	2001/04/04 16:40

	Comments	Error Definition	Errors
1			0
2			0
3			0
4			0
5			0
6			0